

TOOLBOX SAFETY TRAINING

Company _____ Location _____ Date _____

Volume 13 - Number 36 ELECTRICAL FACE PLATES



Safety hazards aren't confined to construction job sites. Sometimes we are so concerned with the construction area that we forget about the office area.

A routine inspection of a company office found this electrical hazard lurking in a back utility room. An electrical outlet that was missing a face plate was located directly under a sink, exposing the wires to possible wet conditions. The outlet was covered by boxes and dirty carpets.

This is an electrical fire hazard waiting to happen.

Always make sure that electrical boxes are properly covered and clear of debris. Don't take chances with electricity.


FIRE HAZARD-
Electrical box was left without a face plate and dirty carpets and boxes were put over it.



TOOLBOX SAFETY TRAINING

Company _____ Location _____ Date _____

Volume 13 - Number 36 ELECTRICAL FACE PLATES



Safety hazards aren't confined to construction job sites. Sometimes we are so concerned with the construction area that we forget about the office area.

A routine inspection of a company office found this electrical hazard lurking in a back utility room. An electrical outlet that was missing a face plate was located directly under a sink, exposing the wires to possible wet conditions. The outlet was covered by boxes and dirty carpets.

This is an electrical fire hazard waiting to happen.

Always make sure that electrical boxes are properly covered and clear of debris. Don't take chances with electricity.

FIRE HAZARD-
Electrical box was left without a face plate and dirty carpets and boxes were put over it.

